


New Connectors For Low Profile Power Supply

RP34L Series



■Features

1. Low profile:

These receptacles are designed with their installation heights to be shorter than those of conventional RP34 series, such as 6.1mm (for 2-core type) and 5mm (for 3-core type). (See Fig.-1.)

2. Space saving:

Both 2 and 3 position receptacles are miniaturized to 7mm in depth, resulting in a small board mounting area. Please refer Fig.-2 and Fig.-3.

3. With snap-lock mechanism:

Audible click when connector is fully mated.

4. Tight fit:

Designed to fit snugly in all three directions.

5. Sequence structure:

The 3 contact type has sequenced mating so that one pin makes contact as a ground terminal before the other contacts engage.

6. No Mismating


Two polarized keys prevent any insertion error.


7. Ease of Mating


An arrow on the top of the plug shows the proper direction for insertion.

■Applications

Notebook PCs, portable remote terminals, AV equipment, etc.







■Product Specifications

	RATINGS	Rated Current	5A	Available Temp. Range	-25℃~+85℃
		Rated Voltage	AC30V,DC42A	Storage Temp. Range	-10℃~+60℃

Description	Specifications	Requirements
1.contact resistance	$30m\Omega$ or less	Should be measured at DC 1A.
2.insulation resistance	1000m $Ω$ or more	Should be measured at DC 100V.
3.voltage resistance	No flashover/dielectric4.vibration Breakdown	AC 150V for 1 minute
4.vibration resistance	No instantaneous electric Disconnection of 10µs or More	10~55Hz, one-sided amplitude 0.75mm, 3 directions for 2hours, respectively
5.temperature cycle	Insulation resistance:100mΩ or more	-55°C for 30 min.→normal temp. for 10~15 min.→+85°C for 30 min.→normal temp. for 10~15 min. 5 cycles
6.corrosion resistance	No excessive corrosion	For 48 consecutive hours in 5% salt water
7. Duration against consecutive plugging/unplugging.	Contact resistance:60mΩ or less	5,000 time

Note.1) Above-stated specifications are typical of this series. For part specific data, please consult factory.

■Material Quality

Description		Material	Processing	Remarks
	Metal fixture	Phosphor bronze	Solder-plating	
2 position receptacle	Dielectric	Nylon resin	Black color	UL94HB
	Terminal	Brass	Palladium-plating	
	Cover	Vinyl chloride resin	Black color	UL94V-0
2-position plug	Insert insulator	Nylon resin	Black color	UL94HB
	Terminal	Phosphor bronze		
	Metal fixture	Phosphor bronze	Solder-plating	
3-position receptacle	Insulator	PPS resin	Black color	UL94V-0
	Terminal	Brass	Palladium-plating	
	Cover	Polycarbonate resin	Black color	UL94V-0
2 position plus	Cover	Vinyl chloride	Black color	UL94V-0
3-position plug	Insulator	PPS resin	Black color	UL94V-0
	Terminal	Phosphor bronze	Palladium-plating	

■Product Name Configuration


This is available for you to determine the product specifications from a part number, not to produce part numbers. When ordering, please select from existing part numbers shown in page 3-4 of this catalog.[For plugs, Hirose will produce cable assemblies to customer specifications. Please consult Hirose for quote.]

$$\frac{\mathsf{RP34L}}{\bullet} - \frac{5}{2} \, \frac{\mathsf{PA}}{\bullet} - \frac{2}{4} \, \frac{\mathsf{SC}}{\bullet} \quad \frac{(****)}{\bullet}$$

Series name: RP34L	4 Number of positions:		
Shell: 5-shell.size	Shows the number of terminals.2contacts.3 contacts		
€ Type:	5 Type of contact:		
Receptacle: R	PD: dip-solder male terminal		
Assembled straight plug: P	SC: crimp-style female terminal		
Assembled right angle plug: LP	6 Cable length:(****) depends on		
Cable-integrated forming straight	each cable.		
plug: PA			

■Receptacles ●2-position






Recommended panel dimensions (reference)


Hole dimensions for a printed circuit board to be installed






●3-position






Recommended panel dimensions (reference)

Hole dimensions for a printed circuitboard to be installed







HRS No.	Parts No.
113-5154-6-00	RP34L-5R-2PD
113-5157-4-00	RP34L-5R-3PD

■Plugs















HRS No.	Parts No
113-5153-3-00	RP34L-5PA-2SC(1857)
113-5158-7-00	RP34L-5P-3SC
113-5161-1-00	RP34L-5LP-3SC

■Crimp Terminal






HRS No.	Parts No
113-5151-8-01	RP34L-SC1-212(01)

■Applicable Tools

TYPE		HRS No.	Parts No.	Conformant terminal	Conformant Cable
Manua	al crimping tool		HT-102/RP34L-SC1-212	RP34L-SC1-212(01)	AWG#18~#22
Crimpor	Automatic	901-0005-4	CM-105		
Crimper	Crimper body	901-2043-4	AP105-RP34L-SC1-212	RP34L-SC1-212(01)	AWG#18~#22
Cable	e crimping tool	150-0074-1	RP34-TC-01		<i>\$</i> 4
Drawing tool		150-0039-0	RP6-SC-TP		


■ Assembly Instructions (3-Position Plug)

Straight Plug



- 1. First, pull the bushing through the terminal-processed cable to crimp and wire that terminal.
- 2. Insert such crimped/wired terminal into the terminal hole of S insulation P case. Then verify that the crimp terminal is firmly engaged in the terminal hole of S insulation P case by pulling the cable slightly. In such cases as incorrect wiring, insert the drawing jig (RP6-SC-TP) from the fitting section to draw the terminal out of wiring side and rearrange it.
- 3. Next, crimp the clamp to the cable with an applicable tool (RP34-tc-01).
- 4. Install the convex section of S insulation P case in the cord tube(B) by adjusting to its round hole.
- 5. Then put the rim of clamp into the concave section of cord tube(B), and install bushing/clamp in cord tube(B).
- Install cord tube(A) in cord tube(B). At that time, verify that four claw sections of cord tube(B) are mounted on the square hole section of cord tube(A).


●Right Angle Plug




1. The right angle plug can also be assembled by using the same procedure as the straight plug.

■Precautions

1. Use the connector section with its panel held down so as not to have excessive load. For 2-contact type, hold the outer shellsection of the receptacle, and for 3 contact type, the outer shell section of the plug.



2. After connector assembly, cable must not be pulled over 30N in the arrow-indicated direction. Be careful not to add excessive tensile load because it will lead the damage of connectors.





HIROSE ELECTRIC CO.,LTD.
5-23,OSAKI 5-CHOME,SHINAGAWA-KU,TOKYO 141-8586,JAPAN PHONE:3-3491-9741 :3-3493-2933