
# Pomona®

## Model 5076 Strain Relief Boot With Clamp Nut



#### **FEATURES:**

- Use with RG58 and RG141 cable.
- Use with connectors having 7/16 28 clamp nut threads.

### **MATERIALS:**

Clamp Nut: Brass Per QQ-B-626, Alloy 360, 1/2 Hard

Boot: PVC, Color: See ordering information

Finish: Clamp Nut: Brass, Nickel Plate Per QQ-N-290, .0002" Min.

### **RATINGS:**

Operating Temperature: +50°C.(+122°F.) Max.

Operating Voltage: 500 VRMS

#### ORDERING INFORMATION: Model 5076 -\*

\*= Color, -0 Black, -2 Red

Ordering Example: 5076-2, Color is Red Additional Colors can be quoted upon request.

All dimensions are in inches. Tolerances (except noted):  $.xx = \pm .02$ " (,51 mm),  $.xxx = \pm .005$ " (,127 mm). All specifications are to the latest revisions. Specifications are subject to change without notice. Registered trademarks are the property of their respective companies. Made in USA

6/9/99 SY/FH/LS Sales: 800-490-2361 Fax: 888-403-3360 Technical Assistance: 800-241-2060 Pomona*ACCESS* **90616** (800) 444-6785 or (425) 446-6010 More drawings available at www.pomonaelectronics.com